



Instructions in case of fire in a controlled area.

- Apply U.L.B. fire safety rules.
  - Notify the Health Physics Department (tel : 02/650.49.47)
  - As far as possible and without endangering yourself, evacuate radioactive sources from the threatened area.
  - If sources cannot be evacuated, fight the fire with powder or CO2 extinguishers; avoid using hose reels.
  - The intervention team will leave the site only after checking for possible contamination.
  - After the fire, access to controlled areas will be forbidden until the premises have been inspected by the Health Physics Department, which will determine whether or not radioactive contamination is present.
- In case of contamination, the Health Physics Department will take appropriate action.

