

## What to do in case of contamination ?

- Immediately notify the Health Physics Department  
(tel : 02/650.49.47) stating :

NAME, first name  
Departement, Laboratory, Campus  
Phone extension  
nature of the incident

*(In case of absence, contact Be.Sure on 010/81.21.83)*

- Quickly take all measures to limit the contaminated area.

- Evacuate the accident site and the exposed personnel, taking care not to disperse contamination.

- Report and mark out the contaminated area.

- Prevent anyone from entering the area until authorized by the Health Physics Department, and notify the cleaning service.

After receiving instructions from the Health Physics Department, access will be granted either in the presence of the RPE, or in the presence of the local RPO.

- If there is no risk of fire, keep ventilation running.

- *If there is a risk of fire*, be sure to close doors and windows.

- Check clothing, shoes, etc. : put contaminated items in identified plastic bags.

- If skin contamination: wash with lukewarm water and mild soap until all contamination has been removed.

In the event of skin or eye contamination, immediately notify the Occupational Medical Service.

- Fill in the radiation protection incident report form (see appendix) available on the Health Physics Department website (<http://www.controlephysique.be>).